



# COVID-19 PRODUCTIVITY REPORT March – June 2020

Citizens Advisory Committee August 19, 2020 Agenda Item #8

#### WFH NOT US? Over 50 projects completed...

- Track Installed new walkway rock at 12 station tracks SF (10)
- Stations New bird netting at Airport Avenue & Taylor Street (13)
- Right of Way New fencing in SF at Iowa St, Pennsylvania & Palou Ave, San Carlos man & vehicle gate (5)
- Communications Dragger equipment software upgrade (13)
- Signal Installed solid state Circuit Controller at 3<sup>rd</sup> Ave (13)




#### TRACK SOGR

- Worked with Operations to utilize NEW Work Windows, as Passenger Service was reduced, our focus was on the following:
  - 1. Track Maintenance
  - 2. Track Upgrades
  - 3. Capital Project Support



### 22<sup>nd</sup> St. Rail Replacement




- Rail fracture at MP 1.60 on the MT2 track, West Rail
- Fracture occurred on
   12/4/2019 under Train number
   102 Southbound
- Track back into service 3 hours later
- Rail produced in early 1970's, standard AREA 136 LB Rail




#### 22<sup>nd</sup> St. Fractured Rail Lab Photos








# 22<sup>nd</sup> St. Rail Replacement




 Approximately 5000 Lineal Feet of rail removed and replaced. With no impact to train operations.



# Thermite Welding in Track










# Thermite Welding in Track









## The Completed Weld






#### New Rail Lubricator at MP 9.51 MT2








### CP Shark Switch 7A Spring Frog Replacement









#### South San Francisco Crossover Removals








# 25<sup>th</sup> Ave. Track Stabilizing Support








### **CP Shark Tie Replacement**



- CP Shark Switch 5 and 5A removed from service
- Long ties(10' -16') removed and replaced with 9' ties to allow for PCEP construction work



### San Mateo Bridges – Walkway Installation



- California Public Utilities Commission(CPUC) issued correction notice
- CPUC walkways were not constructed during the San Mateo Bridges project in 2017
- Minimum of 8:1 sloped ramps required for walkways
- 4 walkways required at each bridge, 16 total



#### Crash Beam Strike At Tilton Ave.



- This is what a bad Friday really looks like...
- Expect the unexpected when working around the railroad



### Questions?

